



Instruction adapter retrofit

	<p>Dispensers till 01-2009 You still have got no drilling in the backside and no milled cable gland.</p> <p>Please drill the passage for the cable gland into the backside.</p>		<p>Dispensers since 09-2009 You have got a drilling in the backside, but you still have got no milled cable gland.</p>
	<p>Please remove the parts of the footbridges as you can see in the both adjoining pictures.</p>		
	<p>Dispensers till 12-2009 The cable gland in the footbridges and the hole in the backside are still standard incorporated.</p>		<p>Please lay the cable like in the picture.</p>
	<p>Please insert the electronic unit into the backside.</p>		<p>Please connect the cable of the inserter adapter with the cable of the mains connection.</p>



INFRATRONIC SOLUTIONS

we think globally

www.infratronic-solutions.com

	<p>Please insert the adapter first at the backside of the housing.</p>		<p>Then, please insert the adapter at the front side of the housing until it snaps in hearable.</p>
	<p>Stow the both connected connectors inside the battery case like shown in the picture.</p>		<p>Now put on the cap of the battery case towards the imprinted direction of arrow.</p>
	<p>Please pay attention, that the cable is led through the milling in the top of the battery case.*</p>		<p>The dispenser is now ready for power supply by mains plug.</p>

*If the milling in the cap of the battery case is not there, please carry out this cut by yourself.

As of 09.12.2009

Tel. 0 60 29 / 303 - 0 / Fax - 29
Steuernummer: 20414220380

Raiffeisenbank Waldaschaff
BLZ: 795 655 68
Kto.: 92 46 01

Gerichtsstand Aschaffenburg
Amtsgericht Aschaffenburg HRB8649

www.infratronic-solutions.com
kontaktlos@infratronic-solutions.com

IBAN: DE75 7956 5568 0000 9246 01
BIC: GENODEF1WAA

Die Ware bleibt bis zur vollständigen Bezahlung unser Eigentum nach BGB §449
Bitte beachten: Diese Rechnung ist gemäß UStG mindestens 2 Jahre aufzubewahren

Ust.-IdNr. DE 228141545
Geschäftsführer: Ralf Weinmann
Jochen Weinmann